

City of Taunton - Cost Estimation for Public Safety Buildings

City Priorities
Priority 1: Program Access
Priority 2: Safety
Priority 3: Approach and Entrance
Priority 4: Access to Goods and Services
Priority 5: Toilet or Bathing Rooms
Priority 6: Additional Access

*Cost Estimate Notes:
- Cost of design is not included
- Does not include costs when note indicates future work
- Labor cannot be estimated for all remedies
- There is no cost noted when it's presumed to be a maintenance issue.
Estimates are intended as a guide to budgeting access modifications and are not intended to be absolutely comprehensive or definitive.

Information Provided by Institute for Human Centered Design										Information Provided by City of Taunton				
FACILITY	REFERENCE #	FD WORK ORDER #	ELEMENT	ISSUE / PHYSICAL BARRIER	LOCATION WITHIN FACILITY	CITY PRIORITY	PRIORITY FOR BARRIER REMOVAL	ACTION FOR BARRIER REMOVAL	ESTIMATED COST OF BARRIER REMOVAL	PROJECT START DATE	PROJECT COMPLETION DATE	RESPONSIBLE FOR BARRIER REMOVAL	BARRIER REMOVED	X
Police Station	P1-1		D. Off-Street Parking Spaces	A.Total # of parking spaces B.Total # of designated accessible spaces D.Min space not provided J.Surface not stable, firm, and slipresistant	parking lot	Priority 3	Approach and Entrance	Establish 2 accessible parking spaces with 1 of them being van accessible.	\$1,750.00	2016	Feb-16	Police Chief	completed	
Police Station	P1-2		A. Door	G.Threshold >1/2" high	vestibule	Priority 4	Access to Goods and Services	Make minor adjustments to excessive thresholds.	\$300.00	2016	Feb-16	Police Chief	completed	
Police Station	P1-6		D. Toilet	C.Flush valve too high or not properly located	unisex toilet room	Priority 5	Toilet or Bathing Rooms	Relocate flush valve so that it meets the accessible height requirements and is located on the open (transfer) side of the toilet.	\$400.00	2016	Feb-16	Police Chief	completed	
Police Station	P1-5	FD-7262	C. Lavatory	E.Exposed plumbing underneath	unisex toilet room	Priority 5	Toilet or Bathing Rooms	Provide protection at pipes.	\$66.00	2016	Feb-16	Police Chief	completed	
Police Station	P1-3		D. Interior Route	A.Carpet not securely attached	lobby	Priority 2	Safety	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Feb-16	Police Chief	completed	
Police Station	P1-8		L. Public Telephones	A.Clear space not provided at telephone B.Non-compliant hardware	lobby	Priority 6	Additional Access	Move furniture to provide clear space at telephone. Install a TTY device on telephone on level 1. Install an ADA-compliant sign that directs to the TTY device. Such device must be accessible and available whenever the payphone is operable.	\$2,550.00	2016	Mar-16	Police Chief	completed	phone removed
Police Station	P1-4		F. Dining or Work Surface	B.Number of accessible tables provided F.Edge or knee clearance at tables not provided	interview room	Priority 4	Access to Goods and Services	Ensure the interview room has an accessible desk no higher than 36" above the floor and with the required clear floor space underneath it.	\$500.00	2016	Mar-16	Police Chief	completed	
Police Station	P1-7				holding cells	Priority 1	Program Access	Holding cells will need to be made accessible when renovated.	\$10,000.00			Police Chief		
Central Fire Station	P52-1		H. Entrance	A.Not connected to an accessible route	entrance	Priority 3	Approach and Entrance	Make one entrance accessible to the maximum extent possible.	\$1,800.00			Fire Chief		
Central Fire Station	P52-2		H. Entrance	A.Not connected to an accessible route	entrance	Priority 3	Approach and Entrance	Renovating a second entrance is most likely structurally infeasible.	\$0.00			Fire Chief		
Central Fire Station	P52-3		C. Ramp (Interior)	J.Handrails not continuous where required	apparatus room	Priority 4	Access to Goods and Services	Reconstruct ramp with a handrail on both sides and a level top and bottom landing.	\$2,000.00			Fire Chief		
Central Fire Station	P52-4		F. Accessory	A.Entrails > 48" height	accessible toilet room	Priority 5	Toilet or Bathing Rooms	Mount a coat hook in the accessible toilet room	\$50.00	2016		Fire Chief		
Weir Street Fire Station	P53-1		H. Entrance	L.Threshold >1/2" high	entrance	Priority 3	Approach and Entrance	Make minor adjustments to excessive thresholds.	\$300.00			Fire Chief		
Weir Street Fire Station	P53-2		D. Interior Route	A.Carpet not securely attached	apparatus room	Priority 2	Safety	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Feb-16	Fire Chief	completed	
Weir Street Fire Station	P53-2		B. Overall Access	A.Turning space not provided B.Accessible plumbing fixtures or stalls not provided C.Accessible Accessories not provided	toilet room	Priority 5	Toilet or Bathing Rooms	Provide a side and rear grab bar.	\$600.00			Fire Chief		
Bay Street Fire Station	M6-023		H. Entrance	A.Not connected to an accessible route	entrance	Priority 3	Approach and Entrance	Provide an accessible graded pathway from the public sidewalk to the Baby Safe-lower drop-off platform. Install a two-way communication system with audible and visible signals.	\$4,250.00			Fire Chief		
East Taunton Fire Station	P55-1		H. Entrance	A.Not connected to an accessible route L.Threshold >1/2" high N.Hardware inoperable	entrance	Priority 3	Approach and Entrance	Install a graded pathway. Ensure that the threshold is no greater than 1/2" and beveled, and replace door knob with lever hardware.	\$2,766.00			Fire Chief		
East Taunton Fire Station	P55-2		D. Interior Route	A.Carpet not securely attached	vestibule	Priority 4	Access to Goods and Services	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016		Fire Chief		
East Taunton Fire Station	P55-3		D. Off-Street Parking Spaces	A.Total # of parking spaces B.Total # of designated accessible spaces C.Minimum number of spaces not provided D.Min space not provided	parking lot	Priority 3	Approach and Entrance	Establish 1 van accessible space. Install sign and stripe access aisle.	\$870.00			Fire Chief		
Oak Street Fire Station	P56-1		D. Interior Route	A.Carpet not securely attached	apparatus room	Priority 2	Safety	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$200.00	2016	Feb-16	Fire Chief	co mpleted	
Oak Street Fire Station	P56-2 a		B. Overall Access	A.Turning space not provided E.Clear floor space not provided in toilet room	toilet room	Priority 5	Toilet or Bathing Rooms	Relocate the toilet 16-18" from the side wall, install rear and side grab bars and toilet paper dispenser that is 7-9 inches in front of the toilet rim between 15 and 48 inches high.	\$2,500.00			Fire Chief		
Oak Street Fire Station	P56-2 b		B. Overall Access	B.Accessible plumbing fixtures or stalls not provide C. Accessible Accessories not provided	toilet room	Priority 5	Toilet or Bathing Rooms	Relocate the toilet 16-18" from the side wall, install rear and side grab bars and toilet paper dispenser that is 7-9 inches in front of the toilet rim between 15 and 48 inches high.	\$2,500.00			Fire Chief		
Oak Street Fire Station	P56-2 c		B. Overall Access	D. Visual & visible alarm not provided	toilet room	Priority 5	Toilet or Bathing Rooms	Relocate the toilet 16-18" from the side wall, install rear and side grab bars and toilet paper dispenser that is 7-9 inches in front of the toilet rim between 15 and 48 inches high.	\$2,500.00			Fire Chief		
Oakland Fire Station	P57-1		D. Off-Street Parking Spaces	A.Total # of parking spaces B.Total # of designated accessible spaces	parking lot	Priority 3	Approach and Entrance	Repair cross slopes at one access aisle and one accessible space, and restripe.	\$870.00			Fire Chief		need to check

Oakland Fire Station	P57-2 a		D. Interior Route	A. Carpet not securely attached	lobby	Priority 2	Safety	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$5.00	2016	Dec-15	Fire Chief	completed	
Oakland Fire Station	P57-2 b		D. Interior Route	A. Carpet not securely attached	side door	Priority 2	Safety	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$5.00	2016	Dec-15	Fire Chief	completed	
Oakland Fire Station	P57-2 c		D. Interior Route	A. Carpet not securely attached	exit	Priority 2	Safety	Secure all weather mats with industrial-strength double-stick tape. Alternatively, replace them with recessed walk-off mats or grates at all entrances.	\$5.00	2016	Dec-15	Fire Chief	completed	
Oakland Fire Station	P57-3	FD-7217	J. Signage	B. Provided, misplaced	unisex toilet room	Priority 4	Access to Goods and Services	Relocate sign on the latch side of the door.	\$50.00	2016	Dec-15	Fire Chief	completed	
Oakland Fire Station	P57-4		C. Lavatory	F. Mirror above lavatory w/ reflective surface > 40"	unisex toilet room	Priority 5	Toilet or Bathing Rooms	Lower the mirror above the accessible lavatory so that its reflective surface is no higher than 40" above the floor.		2016	Jan-16	Fire Chief	completed	
Oakland Fire Station	P57-4	Exposed piping FD-7260	C. Lavatory	E. Exposed plumbing underneath	unisex toilet room	Priority 5	Toilet or Bathing Rooms	Protect the plumbing underneath the lavatory.	\$266.00	2016	Dec-15	Fire Chief	completed	
									\$37,703.00					